

SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-148 **SOP 148**

Issue No. 1 October 2000

SCOPE 1

This document details the application of SOP 148 issued by the Electricity Association.

2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 **ISSUE AUTHORITY**

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-148 **SOP 148**

Issue No. 1 October 2000

SOP DETAILS

TYPE: J & P PDB and PDB-M 11kV and 6.6kV Oil

Filled Circuit Breakers

ORIGINATING REC: Manweb

DATE: 31/5/95

NO INSTALLED IN MANWEB: 1550

STATUS: Restriction

REASON:

Potential for manual trip mechanism to fail resulting in slow opening of circuit breaker.

UPDATE:

REMEDIAL ACTION:

Manual opening restricted to those circuit breakers inspected in accordance with 'Plant Service Bulletin' (No. TBA) dated 22 May 1995.

Electrical operation permitted as the electrical trip mechanism is not affected potential defect.

Manual closing is also acceptable.

Mechanical trip mechanism to be inspected at each maintenance in accordance with 'Plant Service Bulletin' (No. TBA) dated 22 May 1995.