

# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-198 **SOP 198**

Issue No. 1 October 2000

#### **SCOPE** 1

This document details the application of SOP 198 issued by the Electricity Association.

### 2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

<b>Issue Date</b>	Issue No	Author	<b>Amendment Details</b>
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

### 3 **ISSUE AUTHORITY**

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-198 **SOP 198**

Issue No. 1 October 2000

## **SOP DETAILS**

TYPE: REYROLLE ROKSS, ROSSS, ROK, ROS, RMS, RMK

11kV Oil switches, fuse switches and other ring main units

**ORIGINATING REC: SCOTTISHPOWER** 

**DATE:** 11/02/98

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

**STATUS:** The following restriction shall apply to all units of the **RESTRICTION:** 

above type.

No attempt shall be made to open the test access covers, fuse access covers or maintenance access covers whilst any part of the equipment is live.

### **REASON:**

During routine work on a Reyrolle 11kV ring main unit when the cable test access cover on one of the ring switches was opened, a steel spacer barrel became detached from the cover bolt and fell through one of the test prod orifices into the main switch tank.

### **UPDATE:**

**REMEDIAL ACTION:**