


## Troston Overhead Line Grid Connection

Appendix 10.1: Site Photographs

Dec-23 Land and Planning





## **Timber Quality Photographs**



Photograph 1: Plot 6, compartment 15, Glenshimmeroch Forest looking east showing timer quality of Sitka spruce crop, estimated mean volume 400 m³/ha



Photograph 2: Plot 14, compartment 8 Glenshimmeroch Forest, looking west, showing very checked crop, some multiple stems with estimated mean timber volume of 290  $\,\mathrm{m}^3/\mathrm{ha}$ 





Photograph 3: Plot 20, compartment 2, Glenshimmeroch Forest looking west showing good timber crop at the site of the proposed construction compound in the middle of the site. Estimated mean timber volume of 840  $\,\mathrm{m}^3/\mathrm{ha}$ 



## Restock Crop Areas



Photograph 4: Plot 2, Compartment 13, Glenshimmeroch Forest, Looking North Restock Crop, Estimated Three Years Old at.



Photograph 5: Plot 4 compartment 14, Glenshimmeroch Forest Looking West Restock Crop, Estimated Three Years Old at





Photograph 6: Plot 27, Compartment 24, Troston Estate, Estimated. Seven Years Old, Looking North